

REPORT of SURVEY for REPAIRS.

No. 3381 Survey held at London Date Oct 12th 1836
 on the Barb. Barbara Gordon Muster British
 Tonnage 558 Built at St. Mary's When built July 14 1836
 By whom built Peary Owners Gordon & Co
 Port belonging to London Destined Voyage Tobago
 If Surveyed Afloat or in Dry Dock At British Dry Dock

Original Survey, No. 1188 Dated 1836 June 11
 Port London

Repairs. At the present time caulked from the keel up and
Coppered

May 17. 1837 - The condition of this vessel is good & efficient
 & in my opinion entitled to remain in her present class.
George Bayley

The Surveyor to state the present Condition of

Upper Deck Fastenings	_____	Wales	_____
Spirketting	_____	Counter	_____
Plank Shears	_____ <u>Good</u>	Plank and Treenails (Outside to the Water's Edge)	_____ <u>Good</u>
Topsides	_____	Rudder	_____
Upper Deck with its Appendages	_____	Win Hoses	_____
Lower Deck Fastenings	_____	Capstan	_____

General Observations and Opinion,
 as required by the Instructions,

about the good condition
This vessel is well and regularly fastened at the
Hold and Deck Beams and has the appearance
of being a good and substantially built vessel.
George Bayley

The Amount of Fee..... £ 2 : 2 : - is received by me, Geo. B.

Committee Minute _____ 183 _____

Character assigned See Annexed Survey