

3418

# REPORT of SURVEY for REPAIRS.

No. 3418 Survey held at London Date April 14 1857  
 on the Barb Juiana Master Dolling  
 Tonnage 255 Built at Sunderland When built 1831  
 By whom built Pharis Owners Edinburgh Co  
 Port belonging to London Destined Voyage Australia  
 If Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 1090 Dated 1835 - Clap 9 A 1

Port London

### Repairs.

At the present time laying a lower deck, and fitting her as a whaler - altering Main Masthead and shifting Beams to a Caulked throughout and the ship being Ceiling good - Bolting the Butts and putting in one lower Deck Beam and Upper Deck Beam in addition to those already in -

The Hold Beams secured with staple Staps round the Holes - The Beams have a fair and firm appearance & at the present time exposed to the Water

*W. D. Dolton*

mayor to state the present Condition of

Fastenings	} <u>Good</u>	Wales	_____
_____		Counter	_____
_____		Plank and Treennails (Outside to the Water's Edge)	_____
_____		Rudder	_____
_____		Winlass	_____
Fastenings	_____	Capstan	_____

The shaft, Rigging, Sails &c. appear deficient.

Observations and Opinion, The appearance of this vessel are very favorable, required by the Instructions,

In my opinion the vessel to be continued in her present class 9 A 1

*George Douglas*

The Amount of Fee..... £ 1 : 1 is received by me.

Committee Minute 14 June 1857

Character assigned 9 A 1 local & far.