

REPORT of SURVEY for REPAIRS.

3426
PH

No. *346* Survey held at *London* Date *June 7* 1837
 on the *Boche Asia* Master *Peerman*
 Tonnage *573* Built at *Calcutta* When built ~~1817~~ *1815* *Produced at the Office 28th June 1837*
 By whom built _____ Owners *J.B. Bluff*
 Port belonging to *London* Destined Voyage *Sydney*
 If Surveyed Afloat or in Dry Dock *Rep^d in Dry Dock*

Original Survey, No. *162* Dated *1834* *Capit A. 1*
 Port *London*

Repairs. *At the present time stripped, caulked from the keel up*
thoroughly overhauled and repaired. The Chain Bolt
shifted.

The Surveyor to state the present Condition of

Upper Deck Fastenings _____	Wales _____
Spirketting _____	Counter _____
Plank Shears _____	Plank and Treecells (Outside to the Water's Edge) _____
Topsides _____	Rudder _____
Upper Deck with its Appendages _____	Windlass _____
Lower Deck Fastenings _____	Capstan _____

Leads, Rigging, Tails to overhauling

General Observations and Opinion, *This ship presents a very firm and substantial*
appearance throughout & in my opinion is fit
for the service of sea and probable longer
than for all parts of the world should be classed
A. 1

The Amount of Fee £ *3* : *3* : _____ is received by me, *George Bayley*

Committee Minute _____ *30 June 1837*

Character assigned _____ *Best Atlantic second class*

