

4-3437

REPORT of SURVEY for REPAIRS.

J. A. H.

No. 17 Survey held at Sunder Date June 6th 1887
 on the Bk. Ganges Master J. Andie
 Tonnage 447 Built at Calcutta When built 1866
 By whom built _____ Owners J. Andie
 Port belonging to Sunder Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Afloat in the Dry Dock

Original Survey, No. 1070 Dated 1835 Class A.1
 Port Sunder

Repairs. At the present time has been surveyed to find out a leak which proved to be in the bolts of an Iron Sunder Brace over the Copper, which has been replaced with an copper one, the vessel caulked from the Copper upwards, two new lodging pieces & the bottom examined

The Surveyor to state the present Condition of

Upper Deck Fastenings	} <i>Good</i>	Wales	} <i>Good</i>
Spirkettling		Counter	
Plank Shears		Plank and Treennails (Outside to the Water's Edge.)	
Topsides		Rudder	
Upper Deck with its Appendages		Winlass	
Lower Deck Fastenings		Capstan	

General Observations and Opinion, *In good condition firm at her fastenings as required by the Instructions, & I am of opinion may remain in her present shape*
W. Woodroffe

The Amount of Fee..... £ 2 2 0 is received by me *J. A. H.*

Committee Minute 4 July 1887

Character assigned A.1



Lloyd's Register Foundation