

ANNUAL SURVEYS.

3457

No. 2457 Survey held at London Date July 14th 1837
 on the Bk. William King Anderson Master W. Osborn
 Tonnage 309 Built at New Brunswick When built 1827
 By whom built _____ Owners Sturtevant
 Port belonging to London Destined Voyage New York
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 16182266 Port of London 1035 Classed A.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>sound & true</u>	Masts, Yards, &c.
Spirketting	Topsides <u>Good</u>	Sails <u>Good</u>
Plank Shears <u>Good</u>	Wales	Cables <u>Good</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of <u>well found</u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, Have examined this vessel very minutely & can find no appearance as required by the Instructions, if decay is very firm at her fastenings & in good condition between the hull & stow, I am of opinion she may remain in her present state

Committee Minute 10 July 1837
 Character assigned A.1
W. Osborn W. Osborn W. Osborn

No. _____ Survey held at London Date July 13th 1837
 on the Wm. H. H. H. H. Master James B. B. B.
 Tonnage 103 Built at Bristol When built 1835
 By whom built _____ Owners J. Clarke
 Port belonging to Bristol London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 169 Port of Bristol Classed A.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting <u>Good</u>	Topsides <u>Good</u>	Sails <u>Good</u>
Plank Shears <u>Good</u>	Wales	Cables <u>Good</u>
Waterways	Plank & Treenails (Outside to the Water's Edge)	Anchors No. of <u>well found</u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, The above appears a very indifferent built vessel, the arms of the lodgings have rotted, the ceiling is of edge & of inferior quality, all work square & sound & I am of opinion she is not entitled to a higher class than her present one

Committee Minute _____ 1837
 Character assigned A.1
W. Osborn W. Osborn W. Osborn