

REPORT of SURVEY for REPAIRS.

No. 3459 Survey held at LONDON Date July 14 1877
on the Subsrah Merchant Master Moncrief
Tonnage 531 Built at Colintha When built 1818
By whom built - Owners Moncrief
Port belonging to LONDON Destined Voyage Home
If Surveyed Afloat or in Dry Dock Curlew & back

Original Survey, No. 1119 & 2303 Dated 1856 Clipped At 1-
Port LONDON

Repairs. At the present time Shipped nothing
cracked and a coppers

The Surveyor to state the present Condition of

Upper Deck Fastenings
Spirketting
Plank Shears
Topsides
Upper Deck with its Appendages
Lower Deck Fastenings

Wales
Counter
Plank and Treenails
(Outside to the Water's Edge.)
Rudder
Winlass
Capstan

General Observations and Opinion,
as required by the Instructions,

This Ship Antennas sound may in
may in my opinion be improved
clipped At 1
being fit to carry
any other cable longer to 4 from all parts of the
when

The Amount of Fee..... £ 3 : 3 : 0 is received by me.

Committee Minute 1877

Character assigned At 1