

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date July 4th 1857
 on the Ship Robert Merchant Master Monsieur
 Tonnage 531 Built at London When built 1838
 By whom built _____ Owners Monsieur
 Port belonging to London Destined Voyage Robert Town
 If Surveyed Afloat or in Dry Dock Cauling Dry Dock

Original Survey, No. _____ Dated March 1838 Capit. H. I.
 Port London

Repairs. In

The keel of this ship is very deep and in good condition and when the bottom is shipped and recooped will in every respect be sufficient for the safe conveyance of any perishable cargo to all parts of the world.
 The Surveyor to state the present Condition of Yrs Obedt

Upper Deck Fastenings	} <u>Good</u>	Wales	} <u>Good</u>
Spirkettling		Counter	
Plank Shears		Plank and Treennails <small>(Outside to the Water's Edge.)</small>	
Topsides		Rudder	
Upper Deck with its Appen lages		<u>Wales</u>	
Lower Deck Fastenings		Capstan	

General Observations and Opinion, as required by the Instructions,



© 2019

The Amount of Fee.....£ : : is received by me.

Committee Minute _____ 183 _____

Character assigned In annexed Survey

Lloyd's Register Foundation