

REPORT of SURVEY for REPAIRS.

No. 346 Survey held at London Date July 26th 1837
 on the Thames Master Barclay
 Tonnage 454 Built at London When built 1829
 By whom built King Owners Thomson & Co
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Woolwich Dock

Original Survey, No. 18282700 Dated August 12th 1837
 Port London

Repairs. At the present time, the fore most lengths of the
 planks in the topsides (each bow) and the after most lengths
 on each quarter bow, the ship calked and generally
 over hauled.

The Surveyor to state the present Condition of

Upper Deck Fastenings
 Spirketting
 Plank Shears
 Topsides
 Upper Deck with its Appendages
 Lower Deck Fastenings

Wales
 Counter
 Plank and Treenails
 (Outside to the Water's Edge)
 Rudder
 Windlass
 Capstan

Equipment Sufficient & good

General Observations and Opinion, Some of the plank of the topsides fore and
 as required by the Instructions, and on the quarter bow were found slightly decayed
 and were taken out as described above, the same exposed,
 proved very good, I am of opinion they may be continued
 as classed,

The Amount of Fee.....£ 2 : 2 : 0 is received by me. Wm. Barclay

Committee Minute 1837

Character assigned 12 A 1