

REPORT of SURVEY for REPAIRS.

No. 3526 Survey held at London Date April 22nd 1837
 on the By Maria Master Hall
 Tonnage 174 Built at Charter When built 1825
 By whom built Tindale Owners Marshall & Co
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock on the Mags

Original Survey, No. _____ Dated July 1837 Classed "A"
 Port of London

Repairs. At the present time five pair of Iron Diagonal
bars to the side beams, copper plated,
partially caulked

The Surveyor to state the present Condition of

Upper Deck Fastenings	_____	Wales	_____
Spirkettling	_____	Counter	_____
Plank Shears	_____	Plank and Treenails	_____
Topsides	_____	(Outside to the Water's Edge.)	_____
Upper Deck with its Appenlages	_____	Rudder	_____
Lower Deck Fastenings	_____	Winlass	_____
		Copstan	_____

General Observations and Opinion, Is in very good condition throughout and
 as required by the Instructions, am of opinion may remain in her present state

The Amount of Fee.....£ : : is received by me.

Committee Minute _____ 183

Character assigned See annexed Survey