

ANNUAL SURVEYS.

3556

No. 3556 Survey held at London Date July 4th 1837
 on the Schooner Tyro Master Ray
 Tonnage 79 Built at PE Island When built 1834
 By whom built _____ Owners Ray & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock On the Trays

Original Survey, No. 146483200 Port of London 1835 & 1837 Classed E 1

The Surveyor is required to state the present Condition of the

Decks <u>fast & shifter remaining good</u>	Breasthooks <u>Good</u>	Capstan _____
Upper Deck Beams & Fastenings <u>all sound</u>	Transoms _____	Pumps <u>Good</u>
Lower Deck Beams & Fastenings _____	Timbers of the Frame <u>Sound good</u>	Masts, Yards, &c. _____
Spirkettling _____	Topsides <u>2 Upper Strakes of the sides</u>	Sails _____
Plank Shears <u>new & sound</u>	Wales <u>Good from side</u>	Cables _____
Waterways <u>Do</u>	Plank and Treennails <u>good</u>	Anchors No. of _____
Hatchway Comings <u>Good</u>	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper <u>Simple Cotton</u>

General Observations and Opinion, At the present time this vessel has been raised from about 22 or 24 inches
a good deal of the Deck & Sides have been new - To have new thick planks
as required by the Instructions & carried out to the deck & sides & 2 Port Head Tanks and Sides changed
18. 1837. The whole of the Bottom Plank & Sides are overhauled - when the repairs proposed
bottom planks in the Dock are completed I am of opinion that the vessel be entitled to the
4 made good Goodly Clap A. 1

Committee Minute 22 Sept. 1837 George Bayley Dec 1. 1836
 Character assigned Clap A. 1 S.S. 3 4 1837 George Bayley Dec 1. 1837
the vessel is fit

No. 726 Survey held at London Date Sept 5 1837
 on the Schooner Memorialist Master Clark
 Tonnage 173 Built at American When built Prize
 By whom built _____ Owners Barrell
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Mountain Dock trays

Original Survey, No. (No 1100) Port of London March 1835 Classed E 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Good</u>	Capstan _____
Upper Deck Beams & Fastenings <u>"</u>	Transoms _____	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>"</u>	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkettling _____	Topsides _____	Sails _____
Plank Shears _____	Wales _____	Cables _____
Waterways _____	Plank and Treennails _____	Anchors No. of <u>28 15 12</u>
Hatchway Comings _____	Rudder _____	Standing & Running Rigging <u>Good</u>
	Windlass _____	Copper <u>Up & present time</u>

General Observations and Opinion, At the present time putting in some additional work having
as required by the Instructions, been to Deck Beams - She is in my opinion entitled to
remain in her present class A. 1

Committee Minute 10 Sept 1837 George Bayley
 Character assigned A. 1

REVISED EDITION

141. 142.
330. 331.
412. 413.



© 2019

Lloyd's Register
Foundation