

ANNUAL SURVEYS.

3570
G.A.

No. 3570 Survey held at London Date Sept 5 1837
 on the Brig Sustania Master Gibbons
 Tonnage 175 Built at Yarmouth When built 1821
 By whom built _____ Owners Gibbons
 Port belonging to London Destined Voyage Ajaccio
 If Surveyed Afloat or in Dry Dock at Yarmouth

Original Survey, No. 2982 Port of London Nov^r 1836 Classed A.1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Breasthooks <u>good</u>	Copstan _____
Upper Deck Beams & Fastenings <u>very good</u>	Transoms _____	Pumps <u>good</u>
Lower Deck Beams & Fastenings <u>good</u>	Timbers of the Frame _____	Masts, Yards, &c. _____
Deck Planking <u>good</u>	Topsides _____	Sails _____
Stank Sheers _____	Wales _____	Cables _____
Waterways _____	Plank and Treennails _____	Anchors No. of <u>2 1/2 A 1 S A 1 K A</u>
Stowage Comings _____	Rudder _____	Standing & Running Rigging <u>good</u>
	Windlass _____	Copper <u>Single Bottom</u>

General Observations and Opinion. At the present time condition from the keel up and on
as required by the Instructions. few timbers shifted - Her general appearance is fair in
my opinion this entitled to remain classed A.1

Committee Minute 15 Sep 1837 George Bayley

Character assigned A.1 1/2

No. 152 Survey held at London Date Sept 5 1837
 on the Brig Wilkinson Master Archibald
 Tonnage 214 Built at Whitehaven When built 1814
 By whom built _____ Owners Bell & Co
 Port belonging to Whitehaven Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Lineholm Dock

Original Survey, No. 26 Port of Whitehaven & Belfast No 170 1835 Classed A.1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Breasthooks <u>good</u>	Copstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps <u>good</u>
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Deck Planking _____	Topsides _____	Sails _____
Stank Sheers _____	Wales _____	Cables _____
Waterways _____	Plank and Treennails _____	Anchors No. of _____
Stowage Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper <u>1/2</u>

General Observations and Opinion. The appearance of this vessel is favorable and in
as required by the Instructions. my opinion she should remain classed A.1

Committee Minute 16 Sep 1837 George Bayley

Character assigned A.1 1/2

Lloyd's Register
Foundation