

REPORT of SURVEY for REPAIRS.

No. 3590 Survey held at London Date Sept. 27 1887
 on the Bk John Pine Master Mattew
 Tonnage 279 Built at Sunderland When built 1820
 By whom built _____ Owners Mattew
 Port belonging to London Destined Voyage Tunisia
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 957, 1778, 3053 Dated _____ Classed "10 A"

Port Sunderland


Repairs.

At the present time a new Iron Breastwork between the two lower ones twenty-two feet long & two Iron Pinters fifteen long over the fashion timbers & transoms bolted through with copper bolts & screws.

General Observations and Opinion, as required by the Instructions

Is now with the additional fastenings in a very efficient state & fit for the safe conveyance of dry & perishable to remain in her present

Class 10 A

W. M. M. M.


The Amount of Fee.....£..... is received by me.

Committee Minute 28 Sept. 1887

Character assigned 10 A