

ANNUAL SURVEYS.

3599

No. 3599 Survey held at London Date Sept 23 1837
 on the Brig Osborne Master Adams
 Tonnage 162 Built at Plymouth When built 1815
 By whom built _____ Owners Hutton & Co
 Port belonging to London Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock Fountain Dockway

Original Survey, No. 10118 2738 Port of London 1835 Classed A.1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Good</u>	Capstan _____
Upper Deck Beams & Fastenings <u>✓</u>	Transoms <u>✓</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>✓</u>	Timbers of the Frame <u>✓</u>	Masts, Yards, &c. <u>✓</u>
Spirkettling <u>✓</u>	Topside <u>✓</u>	Sails <u>✓</u>
Plank Shears <u>✓</u>	Wales <u>✓</u>	Cables _____
Waterways <u>✓</u>	Plank & Treennails <u>✓</u> (Outside to the Water's Edge)	Anchors No. of <u>2</u>
Hatchway Coverings <u>✓</u>	Rudder <u>✓</u>	Standing & Running Rigging <u>✓</u>
	Windlass <u>New Windlass with Tappacks Patent</u>	Copper <u>largely repaired & painted</u>

General Observations and Opinion.

as required by the Instructions. At the present time this Cathed & general overhaul afloat presents throughout a firm appearance and in my opinion is fit for the service and of dry and perishable cargo to be made.
July 1837

Committee Minute _____

Character assigned A.1 George Douglas

No. 3599 Survey held at London Date Sept 23 1837
 on the Brig William & Alfred Master Drysdale
 Tonnage 338 Built at Hull When built 1811
 By whom built _____ Owners Head
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Abroad Dock

Original Survey, No. 236 1588 Port of London 2724 & 3270 Classed A.1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Good</u>	Capstan _____
Upper Deck Beams & Fastenings <u>✓</u>	Transoms <u>✓</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>✓</u>	Timbers of the Frame <u>✓</u>	Masts, Yards, &c. <u>✓</u>
Spirkettling <u>✓</u>	Topside <u>✓</u>	Sails <u>✓</u>
Plank Shears <u>✓</u>	Wales <u>✓</u>	Cables _____
Waterways <u>✓</u>	Plank & Treennails <u>✓</u> (Outside to the Water's Edge)	Anchors No. of _____
Hatchway Coverings <u>✓</u>	Rudder <u>✓</u>	Standing & Running Rigging <u>✓</u>
	Windlass _____	Copper <u>Sept 1837</u>

General Observations and Opinion.

as required by the Instructions. At the present time Copper examined & a few
 of the afloat is in my opinion suitable to retain
 her present class A.1
Sept 1837

Committee Minute _____

Character assigned A.1 George Douglas