

ANNUAL SURVEYS.

3611

No. 3611 Survey held at London Date 27 Sept 1837
 on the Starbuck Master Phill
 Tonnage 402 Built at London When built 1828
 By whom built Sparks & Co Owners Messrs
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Afloat

472

Original Survey, No. 958 Port of London Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Copstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting <u>Very good</u>	Topsides	Sails <u>Sufficient</u>
Plank Shears <u>London</u>	Wales <u>Very good</u>	Cables <u>and good</u>
Waterways	Plank and Treennails (Outside to the Water's Edge.) <u>Condition</u>	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, The vessel and appurtenances are in perfect order and fit to receive cargo as required by the Instructions, very sound fastenings are found to be in good order
is classed
 Surveyor W. H. M. S. P. H. M.

Committee Minute Sept 20 1837
 Character assigned 12 A 1
W. H. M. S. P. H. M.

No. 42 Survey held at London Date Sept 25 1837
 on the Majestic Master L. Lock
 Tonnage 692 Built at St Johns NB When built 1836
 By whom built St Johns NB Owners Kilmer
 Port belonging to St Johns NB Destined Voyage W
 If Surveyed Afloat or in Dry Dock Afloat

472

Original Survey, No. 1416 & 1505 Port of Liverpool Classed 4 A 2

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Copstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting <u>Very good</u>	Topsides	Sails <u>Sufficient</u>
Plank Shears <u>Condition</u>	Wales <u>Condition</u>	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of <u>2 Bowers Steam Hoys</u>
Hatchway Comings	Rudder	Standing & Running Rigging <u>good</u>
	Windlass	Copper <u>none</u>

General Observations and Opinion, This Ship is in a sound and strong condition and is found to be in good order and fit to receive cargo as required by the Instructions, very sound fastenings are found to be in good order
is classed
 Surveyor W. H. M. S. P. H. M.

Committee Minute Sept 20 1837
 Character assigned 12 A 1
W. H. M. S. P. H. M.