

REPORT of SURVEY for REPAIRS.

No. *3516* Survey held at *London* Date *May 31* 18*74*
 on the *Ship London* Master *Strimble*
 Tonnage *612* Built at *London* When built *1833*
 By whom built *Green & Co* Owners *McLurg & Co*
 Port belonging to *London* Destined Voyage
 If Surveyed Afloat or in Dry Dock *Blackwall Dry Dock*

Original Survey, No. *185* Dated *1834* *Classed 12 A 1*
 Port *London*

Repairs.

*At the present time stripped, caulked from the Keel up
 and thoroughly overhauled both in Hull and Rigging
 Sheathed with Yew or Mahogany upon Paper -
 new Foremast & Bowspout*

The Surveyor to state the present Condition of

Upper Deck Fastenings
 Spirketting
 Plank Shears
 Tupides
 Upper Deck with its Appendages
 Lower Deck Fastenings

Wales
 Counter
 Plank and Treennils
 (Outside to the Water's Edge)
 Rudder
 Windlass
 Capstan

General Observations and Opinion, *This ship is throughout in good & efficient
 as required by the Instructions.*

*condition & in my opinion entitled to remain
 Classed 12 A 1*
George Bayley

The Amount of Fee.....£ *3* : *3* : *0* is received by me. *W. H.*

Committee Minute *3 Dec 1873*

Character assigned *12 A 1*