

REPORT of SURVEY for REPAIRS.

No. ³⁰⁴ 365 Survey held at London Date 30 July Harwood 1837
 on the Charlotte Boylie Master Living
 Tonnage 150 Built at Paris When built 1827
 By whom built _____ Owners Pence
 Port belonging to London Destined Voyage Spain
 If Surveyed Afloat or in Dry Dock Williams' Dock

Original Survey, No. 23688 & 2307 Dated 1836 Copied A.1
 Port London

Repairs. Now New blocks, some pieces in various parts
 of outside plating could be from the copper of upper
 part of the.

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
 Spirketting _____
 Plank Shears A good
 Topides Condition
 Upper Deck with its Appendages _____
 Lower Deck Fastenings _____

Wales _____
 Counter _____
 Plank and Treennils
 (Outside to the Water's Edge) _____
 Rudder A good
 Windlass Condition
 Capstan _____

General Observations and Opinion,
 as required by the Instructions,

This ship is now in good and efficient
condition for the voyage of dry & fresh
cargoes and may be continued as closed

The Amount of Fee £ 1 : 1 : - is received by me. H. H.

Committee Minute 6 Oct 1837

Character assigned A.1