

# REPORT of SURVEY for REPAIRS.

No. *3653* Survey held at *London* Date *Oct 6<sup>th</sup>* 183*7*  
 on the *Barque Elizabeth* Master *Smalher*  
 Tonnage *327* Built at *Newcastle* When built *1826*  
 By whom built \_\_\_\_\_ Owners *Hawkey & Co.*  
 Port belonging to *London* Destined Voyage *West India*  
 If Surveyed Afloat or in Dry Dock *Ship from R. Blackwall*

Original Survey, No. *136 82781* Dated *Sept 12 A 1*

Port *London*

## Repairs.

*As the present time shipper carried from keel to  
 keel - Letted & coppered to same height*

The Surveyor to state the present Condition of

Upper Deck Fastenings	_____	Wales	_____
Spirketting	_____	Counter	_____
Plank Shears	_____	Plank and Treenails (Outside to the Water's Edge.)	_____
Topsides	_____	Rudder	_____
Upper Deck with its Appendages	_____	Windlass	_____
Lower Deck Fastenings	_____	Capstan	_____

*Chart Rigging & Bunkering & Deck as before*

General Observations and Opinion, *The appearance of this ship from end to end & bottom*  
 as required by the Instructions, *in my opinion should retain her present class*

*George Dayley*

The Amount of Fee..... £ *2* .. *2* .. is received by me, *W. H.*

Committee Minute *13 Oct 1837*

Character assigned *12 A 1*