

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date Sept 15th 1887
 on the Ship Sustina Master C Young
 Tonnage 410 Built at London When built 1825
 By whom built Culley & Co Owners Davidson & Co
 Port belonging to London Destined Voyage Grenada
 If Surveyed Afloat or in Dry Dock Ship Culley Dry Dock

Original Survey, No. _____ Dated 1885 Clapped 1241
 Port London

Repairs.

At the present time shipped - Caulked from keel to gunwale and recoppered and Paper

Coppered to 16 feet

The keel is perfectly fair and straight - The copper was free from wrinkles or any indication of breakings -

The Surveyor to state the present Condition of

Upper Deck Fastenings Good
 Spirketting "
 Plank Shears "
 Topsides "
 Upper Deck with its Appendages "
 Lower Deck Fastenings "

Wales Good
 Counter "
 Plank and Treenails "
 (Outside to the Water's Edge.)
 Rudder "
 Windlass "
 Capstan "

General Observations and Opinion,
 as required by the Instructions,

Master & crew handling - This ship is throughout in good condition and in my opinion eligible to be present class 1241

The Amount of Fee.....£ : : is received by me.

Committee Minute _____ 188

Character assigned _____