

ANNUAL SURVEYS.

No. 364 Survey held at London Date Sept 29 1837
 on the Ship Lady Kathleen Master Freeman
 Tonnage 321 Built at London When built 1834
 By whom built Cadogan & Co Owners Hankey
 Port belonging to London Destined Voyage Samaria
 If Surveyed Afloat or in Dry Dock Duckhorn Dry Dock during repair

Original Survey, No. 385 Port of London Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, At the present time in consequence of being struck by a sea, several
 as required by the Instructions, structural shifts, some additional knees put to Post Deck & caulked
from the Copper-plate all damages efficiently repaired - This in my
opinion is the safe condition of the vessel & her cargo to be
repacked of the cargo should remain Classed 12 A 1

Committee Minute Oct 20 1837

Character assigned 12 A 1

As the Surveyor is requested to attend and
by the damage - when they occur at the
is apparent, another person was employed in that service.
Do not allow to be made for the Survey.

No. 36 Survey held at London Date Oct 13 1837
 on the Ship Falcon Master Chidley
 Tonnage 357 Built at Sheff When built 1825
 By whom built Baring & Co Owners Baring & Co
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Thrupp's Dry Dock

Original Survey, No. 2782 Port of London 1836 Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank & Treennails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, At present time caulking Lower Deck & parts of chain Deck
 as required by the Instructions, and the outside from the Copper-plate - She is in my opinion
entitled to retain her present Class 12 A 1

Committee Minute Oct 20 1837

Character assigned 12 A 1