

REPORT of SURVEY for REPAIRS.

No. 3702 Survey held at London Date October 16 1837
 on the Ship Isabell Master G. Brown
 Tonnage 580 Built at London When built 1818
 By whom built Rowland Warwick Owners J. Barker
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Blackwall Dock

Original Survey, No. 2682 Dated 1835 Chap. A. 1
 Port London

Repairs.

At the present time doubled 14 staves below the keel with
 3" Dantzic Deal upon Belt Wood sheathed from thence to the
 keel on Belt & sheathed with Yellow metal to 18 ft below -
 Caulked from the keel up - New Main mast & Rigging
 substituted nearly all the Lower Deck, Lodging keel
 Bolts renewed -

The Surveyor to state the present Condition of

Upper Deck Fastenings Good
 Spirketting Good
 Plank Shears Good
 Topsides Good
 Upper Deck with its Appendages Good
 Lower Deck Fastenings nearly all renewed

Wales Good
 Counter "
 Plank and Treenails "
 (Outside to the Water's Edge.)
 Rudder "
 Winlass "
 Capstan "

Mast Rigging Sails Anchors & Cables good & efficient

General Observations and Opinion, This ship is now in an efficient state of repair for
 as required by the Instructions, the conveyance of deposed perishable cargoes to and from
all parts of the world the ship's service should be classed
A. 1 with the addition George Bauley

The Amount of Fee £ 3 : 3 : - is received by me.

Committee Minute 1837

Character assigned A. 1 Anterior - good repair