

REPORT of SURVEY for REPAIRS.

No. 3763 Survey held at London Date October 30th 1835
 on the Bark Sophia Master W Barclay
 Tonnage 37 1/2 Built at Chapstow When built 1823 (Humbell)
 By whom built Scott & Co Owners J F Green & Co
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. _____ Dated Sept^r 1834 Classed F.1
 Port London

Repairs. At the present time a number of the Lower Deck
 Bolts shifted - one plank of the Truss on the Starboard
 side in way of the bolts taken out - some plank
 shifted under Starboard Quarter in consequence
 of a Rat hole - Upper Courses and Trusses caulked
 Mossheathed and Felted Upper Course

Had put new Plank sheers & new windlass 1834

In the early part of the present year had new Decks
 Scaled Pink.

General Observations
 and Opinion, as
 required by the
 Instructions.

The Hold Beams had worked upon the
 Clamp amidships - it is probable that the
 Bolts now shifted ~~were~~ ^{will} prevent their moving
 for the present. The Timbers where exposed
 sound and in good condition - having all been
 charred before the plank work brought on.
 She is in my opinion in an efficient condition
 to remain classed F.1

George Barclay

The Amount of Fee..... £ : : is received by me.

Committee Minute _____ 183 _____

Character assigned See annexed Survey

J F Green Lubbock & Co