

REPORT of SURVEY for REPAIRS. 8

Change of 37/68
 1837

No. 3768 Survey held at London Date Nov 27th 18 37
 on the SS Concord Master T. Martin

New Tonnage 126 Built at Plymouth When built 1832

By whom built _____ Owners Jacobson & Sons

Port belonging to London Destined Voyage Naples

If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 93 Dated _____ Classed 12 A 1

Port of London

Repairs In good condition

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Cupstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <u>Good</u>
Plank Shears	Counter	Sails <u>Good</u>
Waterways	Plank and Treennails (Outside in the Water's Edge)	Cables <u>well found</u>
Hatchway Comings	Rudder	Anchors No. of _____
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion At the present time is in a very efficient state both
 as required by the Instructions, in the hull & stores & may retain her present Class

The Amount of Fee £ 10 : 6 is received by me 1837

Committee Minute 20 Dec 1837

Character assigned 12 A 1