

REPORT of SURVEY for REPAIRS.

3779

No. 3779 Survey held at London Date 21 Nov 1837
 on the Shr William Foster Master George
 Tonnage 175 Built at _____ When built _____
 By whom built _____ Owners J Barnes
 Port belonging to London Destined Voyage Napier
 If Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 2050, 3028 Dated 1854 Restored 1855 - 5 Years
 Port London Classified A1

Repairs

At the present time walked from the fore at
 and at the stern ends, find numerous & part new
 black stuns

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting <u>Good</u>	Wales <u>Good</u>	Masts, Yards, &c. <u>Support</u>
Plank Shears <u>Condition</u>	Counter <u>Condition</u>	Sails <u>and gear</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

This vessel having undergone the above repairs
 is now in an efficient condition and may be
 continued in class Continued

The Amount of Fee.....£ 1 : 1 : - is received by me, At

Committee Minute 5 Dec 1837

Character assigned See P 5 A 1 second repair