

REPORT of SURVEY for REPAIRS.

8 Change of Registry

No. 3700 Survey held at Lindau Date May 13th 1837
 on the By Selme Master Ashton
 Tonnage 103 Built at Fareham When built 1029
 By whom built _____ Owners Captain J^r
 Port belonging to London Destined Voyage Coast Spain
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 20 Dated 1833 Classed 10 A

Port of Portsmouth

Repairs. In good condition

Dec 9th 1837

*This vessel has now been surveyed by me on
 Charles way, the bottom is in a sound substantial
 condition and may in my opinion be continued
 Classed 10 A*

The Surveyor to state the present Condition of

Upper Deck Fastenings _____ Spiketting _____ Plank Shears _____ Topsides _____ Upper Deck with its Appendages _____ Lower Deck Fastenings _____	Wales _____ Counter _____ Plank and Treennails <small>(Outside to the Water's Edge.)</small> _____ Rudder _____ Winlass _____ Capstan _____
--	---

General Observations and Opinion, Was a very efficient state both regards the
as required by the Instructions, that the Stowage is in a fit manner for the safe conveyance
of dry & perishable Goods
Wm Ashton

The Amount of Fee..... £ 1: 1: - is received by me Wm Ashton
5/12/37

Committee Minute 12 Dec 1837

Character assigned 10 A 1

