

3705

# REPORT of SURVEY for REPAIRS.

No. 3795 Survey held at Londou Date August 26 1836  
 on the Ship David Lyon Master Selby  
 Tonnage 476 Built at Spurwich When built 1819  
 By whom built Selby Bayley Owners Selby  
 Port belonging to Londou Destined Voyage Jamaica  
 If Surveyed Afloat or in Dry Dock Ship "Green" in Dry Dock

Original Survey, No. \_\_\_\_\_ Dated \_\_\_\_\_ 1834 October 21 for 1 year  
 Port Londou

**Repairs.** *At this present time the yellow metal stipples off in consequence of its being decayed But to counter-kill down till it & that treat with yellow metal.*

The Surveyor to state the present Condition of

Upper Deck Fastenings \_\_\_\_\_  
 Spirketting \_\_\_\_\_  
 Plank Shears \_\_\_\_\_ *Good*  
 Topsides \_\_\_\_\_  
 Upper Deck with its Appendages \_\_\_\_\_  
 Lower Deck Fastenings \_\_\_\_\_

Wales \_\_\_\_\_  
 Counter \_\_\_\_\_  
 Plank and Treonails (Outside to the Water's Edge) \_\_\_\_\_ *Good*  
 Rudder \_\_\_\_\_  
 Winlass \_\_\_\_\_  
 Capstan \_\_\_\_\_

General Observations and Opinion, *There is no appearance of rotting or giving way, the yellow metal taken on in 1834 appeared to have lost all its tenacity & to become exceedingly brittle - see my opinion & the survey when present ship*  
 \_\_\_\_\_  
*Selby Bayley*

The Amount of Fee ..... £ 2 : 2 : \_\_\_\_\_ is received by me Selby 1836  
 Committee Minute \_\_\_\_\_ 183 \_\_\_\_\_  
 Character assigned See Annual Survey of America



LON602-0005