

REPORT of SURVEY for REPAIRS.

No. _____ Port of London Date Sept^r 16 1825
 Survey of the Ship Torrestor Master McArthur
 Tonnage 270 By whom built _____ Where built Chapstow
 When built 1827 Owners Wm. Hume & Co Port belonging to London
 Destined Voyage Sebuco
 Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. _____ Dated 4 1825
 Port London

Repairs. *At the present time has been caulked from the mid up and recocked having 3 Stakes of felt under the upper course*

General Observations and Opinion, as required by the Instructions *The bottom of this ship has caulked very finely & does not present any appearance of weakness. She is firm on floor at the waterway seams and beam ends. The bottom plank is generally shifted two between with 6 feet shift. Has 3 Stakes of Thicksuff at the fore end outside. Both hull & materials are in an efficient and proper condition.*

*Henry Matthews
Caulked*

 © 2019 Lloyd's Register Foundation

The Amount of Fee.....£ _____ is received by me _____
 Committee Minute _____ 183 _____
 Character assigned to Annexed Survey

Not to be used as a receipt