

REPORT of SURVEY for REPAIRS.

3815

No. _____ Survey held at London Date 24th 20th 18 37
 on the M. E. Meland Master W. H. H. H.
 Tonnage 399 Built at London When built 1811
 By whom built _____ Owners J. B. Phipps
 Port belonging to London Destined Voyage Samoa
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. _____ Dated _____
 Port _____

Repairs. At Portsmouth in April last - New Relye Strakes
 new port New Relye - great part New keel-nailed
 Two New hold beams & one New upper deck ditto
 New fore piece of keel, - New New upper deck knees
 the ship washed all over fitted Sheathing Stoppers

The Surveyor to state the present Condition of

Upper Deck Fastenings _____	Wales _____
Spirkettling _____	Counter _____
Plank Sheers _____	Plank and Treonails <u>to good condition</u> (Outside to the Water's Edge)
Topsides _____ <u>to good</u>	Rudder <u>new</u>
Upper Deck with its Appendages <u>condition</u>	Windlass <u>good</u>
Lower Deck Fastenings _____	Capstan _____

General Observations and Opinion, There is now in an efficient state of
 as required by the Instructions, repair and in my opinion should
be classed as 1st

The Amount of Fee..... £ : : is received by me.

Committee Minute _____ 183

Character assigned See Surveyor's Report