

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date Nov 1886
 on the Ship Etheldred Master White
 Tonnage 399 Built at London When built 1871
 By whom built Pelletier Owners J. B. Clifford
 Port belonging to London Destined Voyage Samaria
 If Surveyed Afloat or in Dry Dock Afloat in the Dock India Dock

Original Survey, No. _____ Dated 1885 Capital A.1
 Port London

Repairs. *In the Spring of this year in consequence of having been driven ashore several timbers stated to have been shifted. A number of Planks shifted in & some out about the Bidge. Caulked throughout and reclipped fastenings as before*

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
 Spirketting _____
 Plank Shears _____
 Topsides _____
 Upper Deck with its Appendages _____
 Lower Deck Fastenings _____

Wales _____
 Counter _____
 Plank and Treemails _____
 (Outside to the Water's Edge)
 Rudder _____
 Windlass _____
 Copstan _____

General Observations and Opinion, *The above report of Repairs is the substance of the examination as required by the Instructions, of the repairs which I recorded in consequence of damage since the Repair has been performed. I have made a voyage to Samaria from her appearance & have come away to believe that the ship is sufficiently repaired and that she is fully entitled to receive a classed B.1*

The Amount of Fee..... £ : : is received by me, George Bayley

Committee Minute _____ 183 _____

Character assigned See Inspected Survey