

REPORT of SURVEY for REPAIRS.

No. 3029 Survey held at London Date 5th Nov 1837
 on the Wm. H. Underwood Master Moffatt
 Tonnage 315 Built at Exwick When built 1818
 By whom built J. Bayly Owners Rugby Bodminster & Co
 Port belonging to London Destined Voyage to India
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 5428 Dated 1836 Classed B.1
 Port London

Repairs found some copper upraised new pillars
to beams -

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions.

This Ship is in good and substantial condition for the carriage of dry & perishable cargoes to and from all parts of the world and may be classed *B.1

The Amount of Fee £ 2: 2: - is received by me for

Committee Minute 26 Dec 1837

Character assigned Fit to receive repairs