

# REPORT of SURVEY for REPAIRS.

3907  
HLL

No. 3907 Survey held at London Date Jan 4 31 1838  
 on the Boat Westminster Master Holison  
 Tonnage 611 Built at Sunderland When built 1837  
 By whom built Laing Owners J. Dunbar  
 Port belonging to London Destined Voyage China  
 If Surveyed Afloat or in Dry Dock Afloat in City Canal

Original Survey, No. 841 Dated \_\_\_\_\_ Classed 10  
 Port Sunderland

Repairs — The Iron Deck Stairs and 11. Gain and  
now put as directed by the Committee  
George Bayley


At 2.14<sup>th</sup> at the present time Docked, a bell's Motters  
caused ~~to be~~ & shaked ~~the~~ with  
yellow metal when Patent Hemp Ribs to  
Wet Bricks.

George Bayley

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,  
 as required by the Instructions,



© 2019

The Amount of Fee.....£ : is received by me,

Committee Minute 20 Feb 18 38

Character assigned 10 A 1

Lloyd's Register  
 Foundation