

REPORT of SURVEY for REPAIRS.

No. 3941 Survey held at London Date February 26th 1838
 on the Back British Isles Master James Muirhead
 Tonnage 1748 Built at Amdurand When built 1837 August
 By whom built Edm Gales Owners Thoschie
 Port belonging to London Destined Voyage Dumman
 If Surveyed Afloat or in Dry Dock Ship 2 furlings Dry Dock

Original Survey, No. 758 Dated August 183 Classed 10A1
 Port Lundeland

Repairs at the present time caused from the keel up and
copied to the stake below the rails upon Patent Hair

This is a substantial and well built vessel and is
fully entitled to her class 10A1 - but cannot in my
opinion be raised to 11A consistently with the Rules

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Cupstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions.

In my opinion this ship should remain
as classed 10A1
George Bayley

The Amount of Fee.....£ 2 : 2 : - is received by me AS

Committee Minute 9 March 1838

Character assigned 10A1