

REPORT of SURVEY for REPAIRS.

3665

No. 3965 Survey held at London Date March 9th 1830
 354 on the By London Master Barnet
 Tonnage 230 Built at Wickton When built 1819
 By whom built _____ Owners Taylor Mosely & Co.
 Port belonging to London Destined Voyage Hambur
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 2158, 2817 Dated 1836 Classed A. 1
 Port of London

Repairs In October last had part of the sheer stake, four
 new planks in the bottom all defective keeneails
 driven out, & caulked from the Keel to the Gunwale
 & a general overhaul—

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling <u>Good</u>	Wales <u>Good</u>	Masts, Yards, &c. <u>Mast</u>
Plank Shears	Counter <u>By strand</u>	Sails <u>Grand</u>
Waterways <u>Turn</u>	Plank & Treennails (Outside to the Water's Edge) <u>Subscribers</u>	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	<u>Copper</u>	Standing & Running Rigging

General Observations and Opinion, This is very good condition both in the hull & stores
 as required by the Instructions. My opinion may remain as Capt. A. 1

The Amount of Fee.....£ 1 : 1 : — is received by me AS

Committee Minute 16 March 1830

Character assigned A. 1 renew repairs