

REPORT of SURVEY for REPAIRS.

3976

JS

No. 37 Survey held at London Date March 10th 1838
 on the Schooner Teazer Master A. Smith
 Tonnage 137 Built at Hastings When built 1834
 By whom built _____ Owners J. S. Adam
 Port belonging to London Destined Voyage Lake Selbachals
 If Surveyed Afloat or in Dry Dock Ship^r - Backwoods Dry Dock

Original Survey, No. 801 Dated _____ 1834 Classed 12 A 1
 Port London

Repairs *at the present time stiffer, Caulked from the keel up and
 reoppered to 10 feet - generally substantiated*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails <small>(Outside to the Water's Edge)</small>	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

} Good

} Good

} Good sufficient

General Observations and Opinion,
 as required by the Instructions,


*This vessel is in an efficient state and in my opinion
 should retain her present class 12 A 1*

George Bayley

The Amount of Fee..... £ - 10 : 6 is received by me, *JS*

Committee Minute 20 March 1838

Character assigned 12 A 1 *Good copy*



LON602-0228