

REPORT of SURVEY for REPAIRS.

No. *4035* Survey held at *London* Date *March 30* 18 *36*
 on the *Ship Woodbridge* Master *Roster*
 Tonnage *576* Built at *Calcutta* When built *1809*
 By whom built _____ Owners *Robt & Co*
 Port belonging to *London* Destined Voyage *Sydney*
 If Surveyed Afloat or in Dry Dock *Limickiln Dock*

Original Survey, No. *2628, 3027* Dated

1836 Classed *A 1*

Port *London*

Repairs

At the present time a Poop has been put upon her well secured - 2 pair of Iron Hanging Beams put to the lower deck, (fourmork beams) - New horse Deck laid - and several scuttles opened in the side - Copper raised to the trade

When the Keel has been opened her frame was found in sound & good condition

The Surveyor is also required to state the present Condition of the

Decks <i>Good</i>	Transoms <i>Good</i>	Windlass <i>Good</i>
Upper Deck Beams & Fastenings <i>Good</i>	Timbers of the Frame <i>"</i>	Capstan <i>"</i>
Lower Deck Beams & Fastenings <i>Do</i>	Topsides <i>"</i>	Pumps <i>"</i>
Spirketting <i>Good</i>	Wales <i>"</i>	Masts, Yards, &c. <i>Rehauls</i>
Plank Shears <i>"</i>	Counter <i>"</i>	Sails <i>Good</i>
Waterways <i>"</i>	Plank & Treenails (Outside to the Water's Edge) <i>"</i>	Cables <i>"</i>
Hatchway Coverings <i>"</i>	Rudder <i>"</i>	Anchors No. of <i>3. 1. 1</i>
Breasthooks <i>Strongly repaired</i>	Copper <i>1836</i>	Standing & Running Rigging <i>Good</i>

General Observations and Opinion,
as required by the Instructions.

This vessel presents a firm & substantial appearance, though her
 in my opinion is fit for the safe conveyance of dispatchable
 cargo to & from all parts of the world & should be classed *A 1*

George Bayley

The Amount of Fee.....£ 3 : 3 : - is received by me, *tho*

Committee Minute

Character assigned