

ANNUAL SURVEYS.

41035

No. 4038 Survey held at Tonam Date 4 April 1838
 on the Sisters Master Ramsay
 Tonnage 260 Built at Hull When built 1810
 By whom built Trager Owners Trager
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 5183465 Port of London

Classed A.1

The Surveyor is required to state the present Condition of the

Decks <u>In good Condition</u>	Breasthooks <u>In good order</u>	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame	Masts, Yards, &c. <u>Sufficient</u>
Spurkitting	Topsides	Sails <u>and good</u>
Plank Shears <u>Good</u>	Wales <u>Good</u>	Cables <u>and good</u>
Waterways	Plank and Treennails <u>Condition</u> (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings <u>Condition</u>	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions,

Some new Plankings, New break 1. Quarter
deck, New Burst Hook. is in good
condition and fit for the carriage of my and
passable cargo and may be

Committee Minute 10 April 1838

Character assigned

A.1 Continued as before
Good

No. 246 Survey held at London Date 4 April 1838
 on the Ajax Master Bruton
 Tonnage 303 Built at Bristol When built 1831
 By whom built Adams Owners Adams
 Port belonging to London Destined Voyage Samoa
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 153 Port of Bristol

Classed A.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>Sufficient</u>
Spurkitting	Topsides	Sails <u>and good</u>
Plank Shears <u>Condition</u>	Wales <u>Condition</u>	Cables <u>and good</u>
Waterways	Plank and Treennails <u>Condition</u> (Outside to the Water's Edge)	Anchors No. of <u>hook 3 BA & 7c</u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions,

The is throughout in the best condition
and may be continued as before

Committee Minute 10 April 1838

Character assigned

A.1 Continued as before
Good

Lloyd's Register
 Foundation

LON402-0294