

ANNUAL SURVEYS.

~~1838~~
1846

No. 406 Survey held at London Date 2 May 1838
 on the William Money Master Boucher
 Tonnage 233 Built at Calcutta When built 1830
 By whom built _____ Owners Green jars
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock at Dock

Original Survey, No. 406 Port of London Classed *A, 1

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps <u>5 goods</u>
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. <u>all good & efficient</u>
Spirketting _____	Topsides _____	Sails <u>Three sets</u>
Plank Shears _____	Wales _____	Cables <u>284 fms Chain 100% 1.54</u> <i>Number</i>
Waterways _____	Plank & Treenails <small>(Outside to the Water's Edge)</small> _____	Anchors No. of <u>3 B. 2. 6</u>
Hatchway Comings _____	Rudder _____	Standing & Running Rigging <u>good</u>
	Windlass _____	Copper _____

General Observations and Opinion, as required by the Instructions, *is complete in her equipment except that the masts and rigging are worn out and unserviceable and proposed to be left Boucher who said he would go to London and order a new set*

Committee Minute _____ 183

Character assigned Soundly

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Original Survey, No. _____ Port of _____ Classed _____


The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirketting _____	Topsides _____	Sails _____
_____ shears _____	Wales _____	Cables _____
Waterways _____	Plank & Treenails <small>(Outside to the Water's Edge)</small> _____	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper _____

General Observations and Opinion, as required by the Instructions, _____

Committee Minute _____ 183

Character assigned _____



© 2019

Lloyd's Register
Foundation

LON 602-0302