

# REPORT of SURVEY for REPAIRS.

4058

*LL*

No. *4058* Survey held at *London* Date *April 10<sup>th</sup>* 18*30*.  
 on the *By Enterprize* Master *Fern*  
 Tonnage *150* Built at *Dartmouth* When built *1815*  
 By whom built \_\_\_\_\_ Owners *J Combs*  
 Port belonging to *Bridgewater* Destined Voyage *Hydr Bay*  
 If Surveyed Afloat or in Dry Dock *Afloat*

Original Survey, No. *109* Port of *Belfast* Dated *2405* Classed *AE 1*  
 Port of *London*

**Repairs** This vessel as I certify has been nearly rebuilt at  
*Newfound London 1833* which from her general good  
 appearance is correct, *additional*  
 At the present time one new Breasthook & caulked

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
per Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <i>Well</i>
Plank Shears	Counter	Sails <i>found</i>
Waterways	Plank and Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, *Was a very efficient state throughout & very firm &*  
 as required by the Instructions, *her fastenings and well found in stores. I am of opinion*  
*is fit for the safe conveyance of any goods that can be*  
*by from all parts of the world & may be classed #AE 1*

The Amount of Fee.....£ *1* : *1* : *1* is received by me *Widdleton*

Committee Minute *14 April 1830*

Character assigned *AE 1*