

1095
D.A.

REPORT of SURVEY for REPAIRS.

No. 1095 Survey held at London Date 9 April 18 35
 on the "Amora" Master Cox
 Tonnage 350 Built at India When built 1817
 By whom built _____ Owners James Cox
 Port belonging to London Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock E. B. Hoek

Original Survey, No. 1304 Dated _____ Classed N. 1
 Port London

Repairs *At the present time Topsides & Sheer Stakes
 have been with African Oak New Plank Sheer
 Sheer generally overhauled and Caulked*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treeneils (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, *This Ship is now double from the keel
 to the gunwale and is in the most
 efficient condition for the conveyance of my 4
 penitentiary troops to any part of the world and
 may be classed N. 1*

The Amount of Fee..... £ 3 : 3 : is received by me James Cox
 Committee Minute 27 April 1835
 Character assigned N. 1 Stores - general repairs

LOW 602-0357