

REPORT of SURVEY for REPAIRS.

No. 4095 Survey held at London Date April 28 1838
 on the Ship Aurora Master Cox
 Tonnage 550 Built at Chittagong When built 1817
 By whom built _____ Owners Hornes
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock East Country, W. I. Dock & Blackette Dry Dock

Original Survey, No. _____ Dated 1835 Classed A. 1
 Port London

Repairs

At the present time stiffer, Caulked from keel up - ~~the~~
 New Plank sheers fore and aft, the midship bulk being cut down
 One Plank of the Deck shifted - Doubling from the former
 doubling up to gun wale - Thoroughly overhauled -

The Timbers seen aloft were sound and in good
 Condition

The Surveyor is also required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Windlass _____
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Good</u>	Capstan <u>Caulkhauling</u>
Lower Deck Beams & Fastenings <u>Good</u>	Topsides <u>Doublet 1838</u>	Pumps <u>Good</u>
Spirkeretting <u>Good</u>	Wales <u>Good</u>	Masts, Yards, &c. <u>Overhauled & new masts</u>
Plank Shears <u>New</u>	Counter <u>Good</u>	Sails <u>3 parts</u>
Waterways <u>Good</u>	Plank and Treennails (Outside to the Water's Edge) <u>Good</u>	Cables <u>Good & efficient</u>
Hatchway Comings <u>Good</u>	Rudder <u>Good</u>	Anchors No. of <u>3. 1. 1</u>
Breasthooks <u>Good</u>	Copper <u>Plated to brass 1838</u>	Standing & Running Rigging <u>Overhauled - good</u>

General Observations and Opinion,
 as required by the Instructions,

In my opinion this Ship is fit for the conveyance
 of dry stowable cargoes to & from all parts of the world
 & should be classed *A.

George Bayley

The Amount of Fee £ : : is received by me,

Committee Minute _____ 18

Character assigned See annexed Survey