

# REPORT of SURVEY for REPAIRS.

*Change of Owners*

No. <sup>108</sup> *1149* Survey held at *London* Date *May 11<sup>th</sup>* 18*30*  
 on the *Bg Adelaide* Master *H. Grieco*  
 Tonnage *250* Built at *Dundee* When built *1831*  
 By whom built \_\_\_\_\_ Owners *Grose & Co*  
 Port belonging to *Sydney* Destined Voyage *Sydney*  
 If Surveyed Afloat or in Dry Dock *Afloat*

Original Survey, No. *130* Dated *1835* Classed *of A 1*  
 Port *of Dundee*

Repairs *At the present time caulked*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, *Is in a very efficient state for the safe conveyance*  
 as required by the Instructions, *dry and fireable cargoes and may retain her*  
*Present Class of A 1*

The Amount of Fee.....£ *1: 1: -* is received by me, *H. Grieco*

Committee Minute *15 May 1830*

Character assigned *A 1*