

REPORT of SURVEY for REPAIRS.

Chambers of Deputies

No. 4150 Survey held at London Date Oct 14 1837
 on the Brig Defiance Master Robt Baker
 Tonnage 142 Built at Shields When built 1824
 By whom built _____ Owners Muskhett
 Port belonging to Blackney Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Falshant's Quay

Original Survey, No. _____ Dated 1835 Clapton 11A1
 Port London

Repairs. At the present time some of the Head ~~Remains~~
 The Cabin Windows shut in, caulked from keel to
 gunwale and thoroughly overhauled both plank and
 Trencils - ~~Remains~~ about 500 Trencils shifted.

This vessel appears perfectly sound and good in all
 parts which came under examination

Now single Bottom

The Surveyor to state the present Condition of	
Upper Deck Fastenings <u>Good</u>	Wales <u>Good</u>
Spirketting <u>"</u>	Counter <u>"</u>
Plank Shears <u>"</u>	Plank and Trencils <u>"</u>
Topsides <u>"</u>	(Outside to the Water's Edge)
Upper Deck with its Appendages <u>"</u>	Rudder <u>"</u>
Lower Deck Fastenings <u>"</u>	Windlass <u>"</u>
	Capstan <u>"</u>

Short Sails Rigging Anchors & cables good sufficient
 General Observations and Opinion, In my opinion this vessel is entitled to remain
 as required by the Instructions, Clapton 11A1

The Amount of Fee..... £ : : is received by me.

Committee Minute _____ 183

Character assigned See annexed Survey

Lloyd's Register
Foundation