

REPORT of SURVEY for REPAIRS.

Change of Owners

4150

No. 4150 Survey held at London Date May 14th 1880
 on the Bg. Sepiance Master W. H. Parker
 Tonnage 142 Built at Shields When built 1827
 By whom built _____ Owners Musket & Co. ☒
 Port belonging to Bag Destined Voyage Dantzic
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1034 Dated _____ Classed 11 A 1
 Port London

Repairs

In very good condition
Need Planks & Riggering and caulking in 1837
The Copper stripped off in July 1837

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frames	Capstan
Lower Deck Beams & Fastenings	Top-sides	Pumps
Spirketting	Wales	Masts, Yards, &c. <i>With new</i>
Plank Shears <i>Good</i>	Counter <i>Good</i>	Sails <i>found</i>
Waterways	Plank and Treennails (Outside to the Water's Edge)	Cables
Hatchway Coverings	Rudder	Anchor No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, *In a very efficient state and may continue her*
 as required by the Instructions, *present ship*

The Amount of Fee.....£ : : is received by me,

Committee Minute 15 May 1880

Character assigned 11 A 1

© 2013

Lloyd's Register
 Foundation

LONG 602-0914