

REPORT of SURVEY for REPAIRS.

No. 1174 Survey held at London Date May 14th 1888
 on the Chorus Fera Master _____
 Tonnage 162 Built at Shrewsbury When built 1828
 By whom built J. B. Baily Owners Hatkins & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Collins Dock

Original Survey, No. 10184 Dated July 1837 & 1834 Classed A1
 Port London

Repairs at the present time caulked from the keel to the
Plankstern and recoppered upon Paper to 11 feet
generally overhauled

The Surveyor is also required to state the present Condition of the

| | | |
|-------------------------------|---|----------------------------|
| Decks | Transoms | Windlass |
| Upper Deck Beams & Fastenings | Timbers of the Frame | Capstan |
| Lower Deck Beams & Fastenings | Topsides | Pumps |
| Spirketting | Wales | Masts, Yards, &c. |
| Plank Shears | Counter | Sails |
| Waterways | Plank & Treennails (Outside to the Water's Edge) | Cables |
| Hatchway Comings | Rudder | Anchors No. of |
| Breasthooks | Copper | Standing & Running Rigging |

General Observations and Opinion, This vessel is now in an efficient state of repair
 as required by the Instructions, for the conveyance of any perishable cargo her cargo
should remain as classed A1

George Bayley

The Amount of Fee.....£ 1 / 1 / — is received by me, John

Committee Minute 25 May 1888

Character assigned A1