

REPORT of SURVEY for REPAIRS.

4175

No. 1175 Survey held at London Date May 15th 1830
 on the Bk Florence Master H Cuny
 Tonnage 179 Built at Yarmouth When built 1824
 By whom built _____ Owners Thompson & Co
 Port belonging to London Destined Voyage Buenos Ayres
 If Surveyed Afloat or in Dry Dock in the Masts

Original Survey, No. 37 Dated _____ Classed 12 A 1
 Port of Exeter

Repairs In 1836 new bottom caulked & coppered over proper
At the present time Masts & Topsides caulked

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <u>good</u>
Plank Shears	Counter <u>good</u>	Sails <u>by</u>
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables <u>well frayed</u>
Hatchway Comings	Rudder	Anchors No. of _____
Breasthooks	Copper	Standing & Running Rigging _____

General Observations and Opinion, Is in a very high state of repair & efficiency and
as required by the Instructions, may retain her present class

© 2019
 W. Middleton

The Amount of Fee.....£ 1 : 1 : - is received by me, H Cuny

Committee Minute 25 May 1830

Character assigned 12 A 1 good after

LON602-0446