

REPORT of SURVEY for REPAIRS.

Change of Property

No. 1476 Survey held at London Date April 27 th 1850
 on the By Hollisport Master Burn
 Tonnage 162 Built at Yarmouth When built 1820
 By whom built _____ Owners H. Hill & Co.
 Port belonging to Rochester Destined Voyage Eastwards
 If Surveyed Afloat or in Dry Dock _____

Original Survey, No. 872-1933 236 & 244 Dated _____ Classed 10 1
 Port of London

Repairs Caulked & several new stunnails

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchor No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, Is in an efficient state for the safe conveyance of
 as required by the Instructions, any & perishable cargoes & may continue in her
present class

The Amount of Fee.....£ : : is received by me,

Committee Minute 25 May 1850

Character assigned 10 A