

REPORT of SURVEY for REPAIRS.

4186

No. 1186 Survey held at London Date 25th May 1838
 on the Thurlii Master Agar
 Tonnage 756 Built at Calcutta When built 1812
 By whom built — Owners J Bond
 Port belonging to London Destined Voyage A S Wales
 If Surveyed Afloat or in Dry Dock Gordons Dock

Original Survey, No. 2642 Dated 1816 Classed A1
 Port London

Repairs

At the present time shipped consisted from the keel up and also lower deck, and generally overhauled, Channels taken down and refitted, &c, &c, &c, to the wales, culm, &c, &c.

The Surveyor is also required to state the present Condition of the

Decks <u>in good condition</u>	Transoms <u>—</u>	Windlass <u>Rudder yards</u>
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>—</u>	Capstan <u>no</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>—</u>	Pumps <u>do</u>
Spirkettling <u>—</u>	Wales <u>In good condition</u>	Masts, Yards, &c. <u>in good condition</u>
Plank Shears <u>—</u>	Counter <u>—</u>	Sails <u>different & good</u>
Waterways <u>in good condition</u>	Plank and Trenails (Outside to the Water's Edge) <u>—</u>	Cables <u>sufficient</u>
Hatchway Comings <u>condition</u>	Rudder <u>—</u>	Anchors No. of <u>3 B 1 B 1 H</u>
Breasthooks <u>—</u>	Copper <u>new</u>	Standing & Running Rigging <u>good</u>

General Observations and Opinion, as required by the Instructions,

She is a strong substantial ship, every where sound and well fastened, fit for the service of duty and particularly adapted to and from all parts of the world, and may be classed A1 Hombury

The Amount of Fee.....£ 3 : 3 : — is received by me, —

Committee Minute 25th May 1838

Character assigned A1 in good condition