

ANNUAL SURVEYS.

4192

No. 459 Survey held at London Date May 26th 1838
 on the W. de Master Saidley
 Tonnage 459 Built at London When built 1804
 By whom built _____ Owners Smithy
 Port belonging to London Destined Voyage to Adenburgh in ballast
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 22013322 Port of London Classed A

The Surveyor is required to state the present Condition of the

Decks <u>muffint</u>	Breasthooks _____	Copstan _____
Upper Deck Beams & Fastenings <u>firm</u>	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings <u>the</u>	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirketting <u>the</u>	Topsides _____	Sails _____
Plank Shears <u>down</u>	Wales _____	Cables _____
Waterways _____	Plank and Treeneils <u>condition</u>	Anchors No. of <u>good</u>
Hatchway Comings <u>the</u>	(Outside to the Water's Edge.) Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper _____

General Observations and Opinion, This ship had been abandoned, so her white on her
 as required by the Instructions, Loss by fire, and afterwards carried into the port
when she is stated to have put on the present slip and underwent the
necessary repairs, which were but tripling the fastenings as found and the
 Committee Minute 22 May 1838 ship in good condition except the masts
 Character assigned FIT which are to be made new on tomorrow
at about 12 o'clock I am of opinion the
may be consumed or clipped

No. 186 Survey held at London Date May 12th 1838
 on the Hibo Master Sale
 Tonnage 184 Built at Attercliffe When built 1833
 By whom built _____ Owners Sale
 Port belonging to Wales Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Attercliffe

Original Survey, No. 1036 Port of London Classed A

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Copstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirketting <u>the</u>	Topsides _____	Sails _____
Plank Shears <u>condition</u>	Wales _____	Cables _____
Waterways _____	Plank and Treeneils <u>condition</u>	Anchors No. of <u>good</u>
Hatchway Comings _____	(Outside to the Water's Edge.) Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper _____

General Observations and Opinion, This vessel has been aground on two last days
 as required by the Instructions, now examine on the boys & found to have sustained
no damage is in good and efficient condition and may be allowed
 Committee Minute 22 May 1838 to be fitted
 Character assigned A