

# REPORT of SURVEY for REPAIRS.

*Change of Owners*

4194  
M  
H

No. 1034 Survey held at Sunder Date May 23<sup>d</sup> 1830  
 on the Subera, Bristol Master Love  
 Tonnage 121 Built at Sunder When built 1831  
 By whom built \_\_\_\_\_ Owners J. Rogers  
 Port belonging to Sunder Destined Voyage Constantinople  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 58 Dated 1034 Classed 12 A 1

Port of Gloucester

Repairs In 1036 Caulked & Repaired

The Surveyor is also required to state the present Condition of the

|                               |   |                               |
|-------------------------------|---|-------------------------------|
| Decks                         | Transoms  | Winlass                       |
| Upper Deck Beams & Fastenings | Timbers of the Frame                                  | Capstan                       |
| Lower Deck Beams & Fastenings | Top-sides   | Pumps                         |
| Spirkettling                  | Wales   | Masts, Yards, &c. <u>good</u> |
| Plank Shears                  | Counter   | Sails <u>g</u>                |
| Waterways                     | Plank and Treennails<br>(Outside to the Water's Edge) | Cables <u>well</u>            |
| Hatchway Comings              | Rudder  | Anchors No. of <u>four</u>    |
| Breasthooks                   | Copper  | Standing & Running Rigging    |

General Observations and Opinion as required by the Instructions, Ship in a very good state of repair & efficiency and fit for the safe conveyance of Dry & perishable cargo  
 W. Dickson

The Amount of Fee..... £ 10 6 is received by me, W. Dickson

Committee Minute 1 June 1830

Character assigned 12 A 1

© 2019 Lloyd's Register Foundation

LONG-20670