

REPORT of SURVEY for REPAIRS.

4208

No. 4110 Survey held at London Date May 30th 1830
 on the S^r Concord Master T. Martin
 Tonnage 120 Built at Plymouth When built 1832
 By whom built _____ Owners J. Palmer & Co
 Port belonging to Plymouth Destined Voyage Import & Export
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 938 3760 Dated _____ Classed 12 A 1
 Port of London

Repairs All the present time apparatus, etc., carried from
 keel to the gunwale and accipere via proper

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <u>Stk</u>
Plank Shears	Counter <u>Good</u>	Sails <u>frame</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of _____
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinions, as required by the Instructions, is in a very high state of efficiency and may
 continue in her present state

© 2019
 Lloyd's Register

The Amount of Fee.....£ 10:6 is received by me, [Signature]

Committee Minute S. [Signature] 18 30

Character assigned 12 A 1