

Change of Registry

ANNUAL SURVEYS.

4214

No. 4214 Survey held at London Date June 2^d 1838
 on the St. Peter Master
 Tonnage 457 Built at Calcutta When built 1808
 By whom built _____ Owners Homes
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 2628 & 3170 Port of London Classed 111

The Surveyor is required to state the present Condition of the

Decks <u>None 1834</u>	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings <u>good</u>	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings <u>do</u>	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkiting _____	Top-sides _____	Sails _____
Plank Shears <u>good</u>	Wales _____	Cables _____
Waterways <u>condition</u>	Plank and Treennails (Outside to the Water's Edge.) _____	Anchors No. of <u>one good</u>
Hatchway Comings <u>new iron</u>	Rudder _____	Standing & Running Rigging <u>new</u>
	Windlass _____	Copper _____

General Observations and Opinion, Three new half beams 5 pair of iron bars each
 as required by the Instructions, side to lower & upper deck beams new comings
new rigging, mast out & fitted, this generally overhauled is fit
for the service as of day & fresh & new to & from all parts of the

Committee Minute S. Stone 1838
 Character assigned Fit & Steady
 Fee 2.2 Rec'd May 21st 1838

No. 115 Survey held at London Date 4th June 1838
 on the St. Peter Master Macpherson
 Tonnage 220 Built at Scottri When built 1821
 By whom built _____ Owners Lind
 Port belonging to Scottri Destined Voyage Lybon
 If Surveyed Afloat or in Dry Dock Afloat


Original Survey, No. 2357, 2826 & 300 Port of London Classed 1021

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkiting <u>good</u>	Top-sides <u>good</u>	Sails <u>good</u>
Plank Shears <u>condition</u>	Wales <u>condition</u>	Cables <u>condition</u>
Waterways _____	Plank and Treennails (Outside to the Water's Edge.) _____	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper _____

General Observations and Opinion, she is throughout in good and efficient
 as required by the Instructions, condition and may be continued or stopped

Committee Minute S. Stone 1838
 Character assigned 10 A 1



LON 602-0492